

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.

1038.

o Chief Surveyors \_\_\_\_\_ Received from Chief Surveyors \_\_\_\_\_  
VESSEL'S NAME "SEA MONARCH". Report Liv. No. 113150.

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/32.)

ie of Survey DOCKING. When due --

Noted.

*YRM*

25.9.39.

The class is subject to the screw shaft liner and the thrust shaft being renewed before the end of 5,40.



© 2019

Lloyd's Register Foundation

W 311-0159