

report made by anyone else? If so, by whom?

2 E

THIS MARGIN. ACROSS THIS MARGIN. WRITE NOT TO REQUESTED ARE SURVEYORS

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

"ANDANES".

Rpt.

Gms.

No.

21056.

The Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

Assessment to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also set out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points covered in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

COMPLETION OF SPECIAL SURVEY OF ENGINES AND BOILERS FOR S.S. No.

This Survey, due 6,38 now held partly

now

terminated, and the following repairs carried out (due to

):-

When it is submitted the vessel is eligible to remain as classed, with condition of BS 8,39, S 8,39 as recommended.



© 2019

Lloyd's Register Foundation

*J.M.M.*

W312-0096

1.9.39.

*examined properly...*