

Port of CowesJan 1619 29REPORT ON MASTS, SPARS, ~~AND RIGGING~~.

Having, in accordance with your instructions, examined the Masts, ~~Spars, and Rigging~~, and Iron Work of same, of the Comp. Aux. Sc. Sch. "MAID MARION"

I have to report that I found the foremast rotten the mainmast requires to be lifted out to take off mast head iron work to examine mast & repair same if being slack

The main topmast requires to be new other spars to overhaul & iron work to regildenize the main boom which is steel is dented on port side requires to be repaired

Signed, E. G. Woodland, ForemanSee L 0-10-100.

To the Surveyors,
Lloyd's Register of Shipping,
Southampton



© 2019

Lloyd's Register
Foundation

W315-0077