



TELEGRAMS · IDEAL, ERITH.
TELEPHONE · ERITH 543, 544.

PES/PA.


NEW IDEAL HOMESTEADS LTD

DIRECTORS: J. S. E. TODD (CHAIRMAN), SIR THOMAS KEENS, D.L.
JOINT MANAGING DIRECTORS: L. H. P. MEYER, P. E. SHEPHARD.
HEAD OFFICE:

IDEAL HOUSE, CARLTON ROAD, ERITH, KENT.

31st. July, 1934.

E. Carey Esq.,
Clerk to the Classification Committee,
Lloyd's Register of Shipping,
71, Fenchurch Street,
LONDON, E.C.3.



Dear Sir,

I am in receipt of your letter of the
24th. July, with reference to my yacht Marion.

I wrote to you on receipt of your previous
communication, stating that the Marion had not
been in commission for two years, and up to date
has been lying at her moorings. Under these
circumstances I presume it is absolutely unnecessary
to have any survey made, and seeing that the boat
has not been used for some years, I should like to
know whether it is necessary to remove the screw
shaft for examination.

Yours faithfully,

P. E. Shephard
P.E.



© 2020

Lloyd's Register
Foundation

W316-0042

Referred to the Chief Engineer Surveyor

Eo

1 AUG 1934

Also for Mr. Oliver to note



© 2020

Lloyd's Register
Foundation