

5 OCT 1932 1

Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

NAME *Stl S Ykt "MARION"*

Rpt. *Sou*

No. *14819*

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32).

Survey DAMAGE.

Damage through *Grounding & striking a dock wall (Rst 21360)*

repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
newed							
removed and faired or repaired.....							
removed or repaired in place.....							

Other items:- *Vessel placed in drydock, bottom examined, no damage sustained through grounding.*

Striking dock wall:- Bulwarks repaired and minor repairs effected.

As submitted the vessel is worthy to remain as classed with Board of Survey *9.32* as recommended.

*100 A. 1.
9.32 Sou*

In the Y.R.



© 2020
Lloyd's Register
Foundation

W316-0062