

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *Wood Yacht "LILYMAID IV"* Rpt. *Sou.* No. *15937*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

S.S. No. *1* (*due 11.33*)

The S.S. No. *1* has now been held, and the following repairs done due to wear and tear:-

*Vessel placed on a slipway.
Caulking made good and copper sheathing renewed as necessary.*

A new engine has been installed and seatings for same have been fitted in accordance with approved plan.

A new anchor has been supplied and verified

It is submitted the vessel is worthy to remain as classed, with record of Survey *S. 35* and notation of *S.S. Sou 35* and *A.S. Sou. S. 35* as recommended.

*16 A1
S. 35 Sou
S. S. Sou. 35
A. S. Sou. S. 35*

In the Yacht Register



© 2020

Lloyd's Register Foundation

W316-0143