

PUMPING ARRANGEMENT Endorsement.

Shipbuilders: Messrs.

John I. Thornycroft, Ltd
Yard No. 1172

Engineers: Messrs.

Engine No.

Owners: Messrs.

"Motor Yacht"

It is submitted that the plans of
~~Piping~~
~~Pumping Arrangement~~
~~Lubricating oil, and Exhaust, Systems.~~
merits approval, provided the arrangements be as
shown and amended on the plan and the remaining
requirements of Sections 20 and 34 of the Rules (1936-7.)
be complied with so far as they are applicable.


It is concluded that one of the
lubricating oil pumps on each engine is capable
of performing the entire lubricating oil service
for that engine in the event of the other
pump breaking down.

The surveyor should satisfy himself regarding
the oil fuel drainage arrangements in way
of the seating holes.

Return ⁶ plans

Retain copy

Li 15/1/37



Lloyd's Register
Foundation
F.R.B.
13/1/37