

If the vessel has been examined. Also state the amount of deterioration (if any) found in the girders, and of the inner bottom plating, especially in the boiler space.
Last Report, No. 4632 Port Pir

100 Al.
438


TELEGRAMS: TOMEPHY, PIRAEUS.
CODES:
BOE: SCOTTS 10TH ED.

T. N. EPIPHANIADES

SHIPOWNER, BROKER,
COAL & GENERAL MERCHANT,

49, MAKRAS STOAS,

PIRAEUS.



20th July 1939.

Lloyd's Register of Shipping,
Piraeus.

Dear Sirs, Yacht "SURF".

With reference to your favour of the 18th inst. we beg to inform you that the yacht "SURF" since April of last year is laid up in the Island of Skiathos, which, naturally is not a suitable place for the Boiler Survey.

Should the yacht be commissioned we shall do the necessary to pass the Survey.

Yours faithfully,
per T. N. EPIPHANIADES

Theo. Theophanis

The Surveyors,
PIRAEUS.



© 2019

Lloyd's Register
Foundation

W319-0030

(per Sec. 20)
Travelling Expenses (if chargeable) £ 6:0
Received by me, 19.....

Surveyors to Lloyd's Register