

9 JUN 1939

by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

EL'S NAME Twn. Sc.Sch."SONA" Rpt. Sou. No. 17421

remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/92.)

The Southampton Surveyors report this yacht placed on a slipway and the requirements of the 2nd S.S.No.1 due 5,39 complied with.

The bottom has been cleaned and coated, one rudder pintle rebushed, some riveting dealt with and minor local pitting specially treated.

It is submitted the vessel appears worthy to remain as classed with record of survey 5,39 and notations of A.S.5,39 and S.S.No.1-39.

100A1
5,39 Sou.
A.S.Sou.5,39
S.S.Sou.No.1-39

In the Y.R.



© 2019

Lloyd's Register
Foundation

3.6.39

W319-0125