

Signal Letters
Rtg. Schooner.
Number of Masts Two.

Corrected Longitudinal Numeral... 6272.51.

Sailmaker Beaton Bros.

F.E.

Chief Ship Surveyor

Received from Chief Ship Surveyor

NAME SH T.S. M/yht " RHODORA Rpt. San No. 13625

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. —Extract from Sub-Committee's Report, 24/5/92.

verse No.

Depth "d"

ing: Table No.

Description

itudinal No.

Proportions

Length

Depth =

Deck Sheerstrake

Revised Rules

This vessel appears to have been built in accordance with the
and the approved plans, and it is submitted she is eligible to
assess

✠ 100A.1. (Steel). In the Yacht Register

1 D^k Leak

D.T.s a 21' 10 t, D.T. + 17' 645.

BK 7", 5 B.H., Cen, Rlyds A CP.

Shade D^k 151'.

W319-0184



© 2019

Lloyd's Register
Foundation

Stiffeners, Spacing