

1c.10.23.

F.E.

Received by Chief Ship Surveyor .....

Received from Chief Ship Surveyor .....

VESSEL'S NAME Stl Se Sr INANDA Rpt. huc No. 79233

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

<sup>1st</sup> Long Transverse No. 12601 Depth "d" 16.42

Framing: Table No. ✓ Description Bulk angle frames as approved

<sup>2nd</sup> Longitudinal No. 33739

Proportions  $\frac{\text{Length}}{\text{Depth}} =$  13.11

Deck Sheerstrake as approved.

Revised Rules

This vessel appears to have been built in accordance with the Revised Rules and the approved plans, and it is submitted she is eligible to be classed

✠ 100 A.1. (Steel):

2 dks (Stl), 3<sup>rd</sup> dk (Stl) in No 1 Hold.

Cell D.B. 340' 1002t, D.Ta 28' 669t, F.P.T. 68t, A.P.T. 32t.

F.K, 9B.H, Cen, Lloyds A.C.P.

P 33' B 165' F 52'



© 2020  
26.5.25  
Lloyd's Register  
Foundation

W32-0007