

Memo. respecting incomplete survey on
the "EMPIRE DEFENDER"

London 22nd November, 1941.

Reference Classing Letter 14th November 1941.

The Donkey Boiler was not prepared for Survey. It was stated that it had not been in use for approximately three years and that it was not to be used until satisfactorily repaired. No mention of the boiler pressure is recorded in the Register Book and the safety valves were set to the ^{same} ~~steam~~ pressure as mentioned in Newport News Report dated 9th August 1941.

FOR { MR. HILL.
MR. NETTLETON.

2m.1.40.

Surveyor.



Lloyd's Register
Foundation

W32-0089

I have been thinking of you
 and wondering how you are
 getting on. I hope you are
 well and happy. I have been
 very busy lately but I will
 write to you again soon.
 Love,
 H

24 NOV 1941



Lloyd's Register
Foundation