


s.s. "EMPIRE DEFENDER"

Lon.109931.

Before this case receives the consideration of the Committee it is submitted the London Surveyors be requested to state whether the condition of the propeller blades be such as to affect classification and if not, whether their recommendation that the propeller blades should be renewed at the Owners' convenience may be deleted.

Please see  
note as amended



*GA*  
26.10.41.

© 2020

Lloyd's Register  
Foundation

W32-0095