

SURFACE TYPE TROWLERS.

EQUIPMENT LIST.

- 1. vice and bench.
- 1 ratchet brace, 6 drills and stand.
- 1 complete set of spanners including
Light top and bottom end and gland spanners
- Piston rod nut spanner
- Claw spanner for valve spindles.
- Box spanners for piston valve junk rings and piston junk rings.
- 2 moving spanners, 1 large and 1 small.
- 1 set of firing tools
- 2 firing shovels
- 2 trimming shovels
- 1 coal hammer and shaft
- 2 hand hammers and shafts
- 3 chisels
- 2 crosscutts.
- 1 gutting chisel
- 1 caulking tool
- 1 tube rod and brush
- 1 tube scraper
- 3 tube stoppers
- 2 ash buckets
- 1 water bucket
- 1 metal salinometer and can
- 24 bolts and nuts assorted
- 1 thermometer
- 4 files and handles.
- 2 oil feeders
- 2 quart feeders
- 1 saw - all
- 2 ferrule tools for brass ferrules
- 1 brass syringe
- 1 funnel with sieve
- 1 $\frac{1}{2}$ gallon measure
- 2 enclosed engine room lamps
- 1 gauge glass lamp
- 5 hand lamps
- 2 packing hooks and screws
- 3 oil tanks.
- 1 copper hammer
- 1 swab tin
- 5 impermeator ditto
- 6 junk ring studs
- Box spanner for junk ring nuts
- Set of eyebolts
- 2 scouring tins
- 1 pair lamp scissors
- 1 screw driver
- 1 set light blocks and falls.
- 1 box taps and dies
- 2 brooms
- 2 scrapers
- Iron (various sizes)
- 1 engine room clock
- 4 boiler makers tools
- 1 pair of pliers
- 1 cooling hose.

