

5/5 Willoughdale

Enquiry pending  
(Sept 20<sup>th</sup>)

Scully's letter 12<sup>th</sup> Aug. 1948.

Surveyor should state whether the alleged  
strake for which he held this examination  
was from double bottom into the hold or  
was leakage through the shell plating.

McCallum's letter 14<sup>th</sup> Aug 1948.

As Mr Ronald carried out part of this General  
amination (now Rpt 103845) he should have  
agreed the Report with Mr McCallum.

If evidence is required by the Court on  
the condition of the double bottom in way  
of the boiler room, Mr Ronald may also be  
called. X

Suggests these Surveyors be instructed to call at their  
office the day before the enquiry.

16/8

Mr Bryden

X. Mr Pitts M.T. Solomon & Mr Hawkins  
have been consulted on this point and agree that it will  
be sufficient if Mr McCallum brings with him a  
certified extract from Mr Ronald's Journal dealing  
with the examination of the boiler Room Tank. It is not  
unanticipated that this item will be a subject of special attention  
at the Enquiry but if found necessary Mr Ronald could  
be called by telegram.

12/8

17/8

17/8

17/8

17.8.48

W322-0080

Lloyd's Register  
Foundation