

31 DEC 1929

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *Stl S GLOFIELD* Rpt. *SWS* No. *18454*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

Nature of Survey **DAMAGE.**Damage through *heavy weather (flooding of No 3 hold)*, damage caused by anchor

now repaired as follows:-

| | Plates | Frames | R.Frames | Floors | Beams | Str. | Plates | Dk. | Plates |
|--|-------------------------------------|--------|----------|--------|-------|------|--------|-----|--------|
| Renewed | | | | | | | | | |
| Removed and faired or repaired..... | | | | | | | | | |
| Faired or repaired in place..... | | | | | | | | | |
| Other items:- | <i>ceiling renewed in No 3 hold</i> | | | | | | | | |

a stem plate on port side doubled in way of a small hole (caused by the anchor) and the surveyors recommend the plate be renewed at the owners convenience.

It is submitted the vessel is worthy to remain as classed with OUT
record of Survey subject as recommended.

as now, Subject etc

[Signature]
27.12.29
© 2021
Lloyd's Register
Foundation

W328-0180