

Glofield

It is submitted the  
Swansea Surveyors be requested  
to forward their report immediately  
upon the completion of the repairs  
to the Engine stop valve.

W328-0189



© 2021

20/10/29  
Lloyd's Register  
Foundation