

age cases where the ...
red his services for this purpose and to whom and why they were declined

Society's ...
... on ... and ... verified

12 FEB 1942

Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

S NAME.....EMPIRE SPRING

Rpt.....Mch

No.....10870

arks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

For conditions of class see endorsement

6.1.42.

The MANCHESTER Surveyors report (1.42)
the vessel examined afloat and minor repairs effected.

Temporary repairs (cement) effected
to leaky rivets in boundary angle of donkey boiler room bulkhead
in Engine Room (s.s).

The Surveyors recommend permanent repairs
at the next dry docking.

It is submitted the vessel appears worthy
to remain as classed without record of survey, subject as
recommended and as above.

As Now, Subject, etc.



© 2019

Lloyd's Register
Foundation

W33-0031

Have Ventilators and their Coamings been examined

Stringers, Clamps & Shells

ditto.....

Hawser & Warps

Salting
(State if examined.)

ditto.....

Standing and