

1

16 SEP 1941

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

EMPIRE SPRING

Report

Lw.

No. 116570

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

Damage

When due

—

Subject to hatch covers at 2<sup>nd</sup> deck & cargo battens being fitted at the first opportunity (to a bow anchor & 45 fathoms of chain cable being supplied), & to indented shell plate (SS) abreast No 4 hatch & to indented plating etc (P.S.F.) being dealt with at the Owner's convenience

ALS  
16/9/41.



© 2019

Lloyd's Register  
Foundation

W33-0041