

ed the

Steel Screw Steamer

Interstrial Plate, for

length

Attached to outside Plate

Angle...

by Chief Ship Surveyor 15. 5. 17

Received from Chief Ship Surveyor

L'S NAME Stl. Single Sc. Sr. "AYAHA MARU". Rpt. Kob. No. 2005


Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey

The Superintendent of the Tipton Proving House should be requested to furnish particulars of the chain cable for which Certificate No. 46329 was issued.

Dr. F.P.H. 15/5/17



15. 5. 17

© 2020

Lloyd's Register Foundation

Surveyor to Lloyd's Register.

48
70
34
34
✓
✓
244
✓ 2
32
76
76
30

& thickness 55 54