

2500,9,40.

1

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME ATHELFOAM Report LIV. No. 115769

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey DAMAGE When due.....

*Subject to indented shell plates H4 + 5 and G4 + 5 from forward (S.S.)  
being dealt with at the Owners convenience and to secondary means  
of steering being fitted on vessels return.*

*W.S.*  
*31.3.41*



© 2020

Lloyd's Register  
Foundation

W336-0040

*opinion to remain as classed with fresh survey, Blm. 3.41 sub*