

COPY.

Lloyd's Register of Shipping.



Port GIBRALTAR

June 10th, 1940

This is to Certify that

W. J. Matthews

the undersigned Surveyor to this Society did at the request of the Agents, Messrs:Gueret Imossi Ltd, and by consent of the Master Captain I.McCalman, survey the British S/S "Balmore", 1925 tons gross, of Glasgow, whilst anchored at Gibraltar on the above and subsequent dates for repairs to leakage which developed in the Port Main Boiler during a voyage from North African Ports via Gibraltar to the U.K. with a cargo of esparto grass.

I found and recommended as follows:-

Defect.

Port main boiler, Starbd:
C.C., Starbd: back plate flange
leaking at local wastage on
the water side at about the
3rd row of stays.
A similar defect repaired at
Gibraltar by welding in 1938
was examined and found in order.

Repairs effected.

Apply for electric welding
portable plant to go alongside.
Reinforced wastage with electric
welding.
W.P.test applied and found in
good order.
Certificate issued accordingly.

W. J. Matthews

W. J. Matthews.
Lloyd's Register Surveyor.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly performed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."