

S.S. "ROWANPARK".

It is submitted Messrs. Cooper & Greig should be informed that the Glasgow Surveyors maintain that their statement regarding the leakage at the front end bottom beams of both Main Boilers is quite correct.

It should also be pointed out that it would be quite contrary to the practice of the Committee to issue a clean Certificate for a vessel when there still remains some repairs to be carried out, even though they may be slight ones.

In the circumstances there does not appear to be any reason to modify the statements contained in the Secretary's letter of the 14th instant regarding the issuing of a clean certificate in this case.

ARRA

24.1.21.



© 2020

Lloyd's Register
Foundation