

VESSEL'S NAME S.S. EMPIRE WARRIOR ex "BIANCA" Report 29/2/40 No. 20042

THICKNESSES OF PLATING ascertained by drilling, and comparison of same with the original thicknesses.

DECIMALS
The thicknesses are in 1 of an inch.

STRAKE.	AMIDSHIP.				FORWARD.				AFT.				REMARKS.					
	Original Thickness.	Thickness by drilling.		Diminution if any.		Original Thickness.	Thickness by drilling.		Diminution if any.		Original Thickness.	Thickness by drilling.		Diminution if any.				
		Port.	Std.	Port.	Std.		Port.	Std.	Port.	Std.		Port.		Std.	Port.	Std.		
BRIDGE SIDE																		
SPAR SHEER STRAKE K.	43	43	43								45	47						Thicknesses taken at amidships, fore end of 86° 1 Hold & in the vicinity of the tunnel recess aft.
Strake below.....L.	43	43	43								37	37						
MAIN SHEER STRAKE H.	43	47	45			57	47				40	37						
1st Strake below.....G.	43	48	43			60	57				34	34						
2nd ".....F.	43	40	45			57	57				34	37						
3rd ".....E.	43	43	43			57	57											
4th ".....																		
5th ".....																		
6th ".....																		
7th ".....																		
8th ".....																		
9th ".....																		

Drillings at ends to be made in the vicinity of the peak bulkheads.

Survey Fee (per Section 20) £ 50 0 0
FOR CLASSIFICATION.

Fees applied for,
See First

© 2020

Lloyd's Register
Foundation

W 34-0008

Robertson