

REPORT ON ELECTRICAL EQUIPMENT.

(OTHER THAN FOR THE PROPULSION OF THE VESSEL)

Received at London Office

27 JUN 1941

Date of writing Report 4th June 41 When handed in at Local Office.....19..... Port of Middeburgh

No. in Survey held at Harbour Hill on 2nd Date, First Survey 11th Apr. Last Survey 3rd June 1941
Reg. Book. Suppt. (Number of Visits.....5.....)

90981 on the S.S. "EMPIRE MICA" Tons { Gross.....
Net.....

Built at Harbour Hill on 2nd By whom built Furness S.S. Co. Ltd. Yard No. 328 When built 1941

Owners Ministry of Shipping Port belonging to Middeburgh

Electrical Installation fitted by Furness S.S. Co. Ltd. (Elec. Dept.) Contract No. 328 When fitted 1941

Is vessel fitted for carrying Petroleum in bulk Yes Is vessel equipped with D.F. Yes E.S.D. Yes Gy.C. Yes Sub.Sig. Yes

Have plans been submitted and approved Yes System of Distribution 2 wires main and Voltage of supply for Lighting 110

Heating Power 110 Direct or Alternating Current, Lighting Yes Power Yes If Alternating Current state periodicity..... Prime Movers,

has the governing been tested and found as per Rule when full load is suddenly thrown on and off Yes Are turbine emergency governors fitted with a

trip switch as per Rule..... Generators, are they compound wound Yes, are they level compounded under working conditions Yes,

if not compound wound state distance between generators..... and from switchboard..... Where more than one generator is fitted are they

arranged to run in parallel Yes, are shunt field regulators provided Yes Is the compound winding connected to the negative or positive pole

negative Have machines over 100 kw. been inspected by the Surveyors during manufacture and testing..... Have certificates of

test for machines under 100 kw. been supplied Yes and the results found as per rule Yes Are the lubricating arrangements and the construction

of the generators as per rule Yes Position of Generators engine room aft on raised platform

is the ventilation in way of generators satisfactory Yes are they clear of inflammable material Yes, if situated

near unprotected combustible material state distance from same horizontally..... and vertically....., are the generators protected from mechanical

injury and damage from water, steam and oil Yes, are the bedplates and frames earthed Yes and the prime movers and generators in metallic

contact Yes Switchboards, where are main switchboards placed engine room port side aft on

raised platform near generating sets.

are they in accessible positions, free from inflammable gases and acid fumes Yes, are they protected from mechanical injury and damage from water, steam

and oil Yes, if situated near unprotected combustible material state distance from same horizontally..... and vertically....., what insulation

material is used for the panels "Dinscamp", if of synthetic insulating material is it an Approved Type Yes, if of

semi-insulating material (slate or marble) are all conducting parts insulated therefrom as per Rule..... Is the frame effectually earthed Yes

Is the construction as per Rule Yes including accessibility of parts Yes, absence of fuses on the back of the board Yes, individual fuses

to pilot and earth lamps, voltmeters, etc. Yes locking of screws and nuts Yes, labelling of apparatus and fuses Yes, fuses on the "dead"

side of switches Yes Description of Main Switchgear for each generator and arrangement of equaliser switches Double pole

quick break knife switch and double pole fuses.

and for each outgoing circuit Double pole double throw quick break knife switch

and double pole fuses.

Are compartments containing switchboards composed of fire-resisting material or lined as per Rule Yes Instruments on main switchboard 200

ammeters 200 voltmeters..... synchronising devices. For compound machines in parallel is the ammeter connected on the pole opposite to the

equaliser connection..... Earth Testing, state means provided E Lamps coupled to E through 2000 fuses.

Switches, Circuit Breakers and Fuses, are they as per Rule Yes, are the fuses an approved type Yes, are all fuses labelled as

per Rule Yes If circuit breakers are provided for the generators, at what overload current did they open when tested 700, are the reversed current


protection devices connected on the pole opposite to the equaliser connection....., have they been tested under working conditions, and at what current

did they operate..... Joint Boxes, Section Boards and Distribution Boards, is the construction and position as per Rule Yes

Cables, are they insulated and protected as per the appropriate Tables of the Rules Yes, if otherwise than as per Rule are they of an approved type.....

state maximum fall of pressure between bus bars and any point under maximum load 4.4V, are the ends of all cables having a sectional area of 0.04

square inch and above provided with soldering sockets Yes Are paper insulated and varnished cambric insulated cables sealed at the ends Yes



X 34-0030(172)

The Electrical Equipment is installed in accordance with the approved plans and the requirements of the Rules.

All Insulated Conductors are guaranteed to have been tested at the maker's works as specified in the Rules.

The foregoing is a correct description.

FURNESS SHIPBUILDING CO. LIMITED

P. P. G. Power

Electrical Engineers.

Date

17.6.41

COMPASSES.

Minimum distance between electric generators or motors and standard compass *283 feet*

Minimum distance between electric generators or motors and steering compass *280 feet*

The nearest cables to the compasses are as follows:—

A cable carrying *.14* Ampères *on the* feet from standard compass *7* feet from steering compass.

A cable carrying *.14* Ampères *7* feet from standard compass *on the* feet from steering compass.

A cable carrying Ampères feet from standard compass feet from steering compass.

Have the compasses been adjusted with and without the electric installation at work at full power *Yes*

Has the effect of switching on and off circuits, motors and other electro-magnetic apparatus within the vicinity of the compasses been noted *Yes*

The maximum deviation due to electric currents was found to be *his* degrees on *Every* course in the case of the standard compass, and *his* degrees on *Every* course in the case of the steering compass.

FURNESS SHIPBUILDING CO. LTD

J. H. Gower

Builder's Signature.

Date

June 17 1941

Is this installation a duplicate of a previous case *Yes* If so, state name of vessel *"Empire Sold"*

Plans. Are approved plans forwarded herewith *No* If not, state date of approval *6/11/41*

Certificates. Are certificates of test for ~~motors engaged on essential services and~~ generators forwarded herewith *Yes*

General Remarks (State quality of workmanship, whether insulation tests, etc., have been made, opinions as to class, etc.) *The electrical*

equipment of this vessel has been installed under special survey in accordance with the approved plans and the Surveyor's letters. The materials used are of good quality and the workmanship is good. On completion trials of the equipment under working conditions were witnessed and found satisfactory and the insulation resistance of all circuits was measured and found good. This equipment is in my opinion suitable for a classed vessel carrying petroleum in bulk.

Total Capacity of Generators *40* Kilowatts.

The amount of Fee ... £ *25* : - : When applied for, *25/6/1941*

Travelling Expenses (if any) £ : : When received, *19*

J. J. Harrison
Surveyor to Lloyd's Register of Shipping.

TUE. 1 JUL 1941

Committee's Minute

Assigned *See Mdb JE 17054*

Form 439—Transfer. (MADE AND PRINTED IN ENGLAND.)
(The Surveyors are requested not to write on or below the space for Committee's Minute.)

