

2m.9.20.

Empire Tarpon ~~Steel 66~~

~~Steel 66~~

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME Steel 66 "HOPATCONG" Rpt. N.Yk. No. 19673

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey.....

1st Entry

To await freeboard verification form.

The Surveyors should be requested to state if the transverse
Rugs to shell are double for four spaces above tank top & to upper
deck in fore hold as per approved plans.



AS
26-1-21
2020

Lloyd's Register
Foundation

W34-0084

BEAMS, Upper Deck, Single Angle, Bulb Angle,
Plate Tee Bulb or Channel.....

congratulation

Angles on ditto, No.
Plates outside Hatchways