


REGISTER, GLASGOW.

TELEPHONE: CENTRAL 6491 (4 LINES).

Lloyd's Register of Shipping,



95, Bothwell Street, GLASGOW, C.2.

16th October, 1941.

Dear Sir,

In reply to your letter of the 14th instant respecting Glasgow Report No. 64432 on the Steamer "EMPIRE TARPON", I beg to acquaint you that the Surveyor states that the boiler water boxes, stays, drums and tubes were found wasted and the tubes badly blistered.

The main condenser tubes were cracked and wasted in way of packing. The section of tubes between the tube plates was found reasonably good.

I am, Dear Sir,
Yours faithfully,

C. Rhulien

Secretary to the
Glasgow Committee.

The Secretary,
WOKINGHAM.



Lloyd's Register
Foundation

W34-0093

I am, Dear Sir,

Bamb...

(E)

H
R

Submitted the surveyors be
informed that as the survey for
reclassing was held only some 9 months
before the Glasgow survey was commenced, some
explanation of the rapid deterioration indicated
is desired & they should furnish it if possible

J. J. 20/10/11



© 2020

Lloyd's Register
Foundation