

m.11.38.

to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME EMPIRE SPRINGBUCK Report Jck No. 1086

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

(RECLASSIFICATION SURVEY PARTLY HELD.) CONDITION
 en due VESSEL 22 YEARS OLD When proposed to be completed EXAMINED 12.40 (12 mos)

tion of Survey held, &c. the greater part.

complete the S.S:- The D.B. & peak tanks, except as per note below,
 require to be examined and tested, ceiling in holds
 removed for examination, the bunkers, masts, wedges
 (if any) and rigging, and hand pump examined.
 (15 fathoms of chain cable require to be supplied).

PLATING to be DRILLED when
 vessel is 24 years old,
 or at next Special Survey
 thereafter.

S.S. PART HELD

Note The testing of No. 1 D.B. and A.P. tank for damage
 can count towards the Reclassification Survey. (PHL. 8044)

For position re fees for Reclassification - see endorsement 22.1.41.