

2m. 1.18.

1

now Empire Springbuck San Angelo

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

Steel S.S. "WESTMEAD".

Report

Sea.

No. 737

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

When due

The kedge anchor has been dispensed with as a War Emergency Measure at Owners' request.

100 A.1. (Steel).

2 Dks. (Steel).

Cell DB. 349' 1180t. FPT 136 . APT 44t.

FK. 7 BH. Cem. A & CP. P 44. B 115', F 47'.



© 2020

Lloyd's Register

19. 12. 13.

Foundation

Remainder in Holds

Tie Plates, outside Hatchways

1110-4618-0171