



Lloyd's Register of Shipping.

LLOYD'S REGISTER
 Collingwood Buildings, Newcastle-on-Tyne.
LONDON.

REC^d 17 JAN 1924

16th January, 1924.

ANS^d

Reference

Dear Sir,

In reply to your questions regarding my report on the "BRITISH GENERAL", I have to state that the pump room was examined and, as reported, extensive repairs carried out in it. It was not considered necessary to have the plating drilled for thickness.

I am, Dear Sir,

Yours faithfully,

John Brown

The Secretary,
 London.



© 2020

Lloyd's Register
 Foundation

W346-0115

*It is concluded that the pump rooms have been examined
 part of the S.S. & that it was not considered necessary to*

Referred to the Chief Ship Surveyor.

Also for Mr. S. A. Hall to note.

17 JAN 1924

17.1.24



© 2020

Lloyd's Register
Foundation