



Lloyd's Register of Shipping.

342, Argyle Street, Glasgow

17th May 1919

Dear Mr James

Reference

Your letter and Shipping report No 521 Kincaid to hand. And I am surprised to hear you Complaining about extra trouble. I tried in my Shipping reports to make this easier for you.

You are quite right that the tunnel shafts are properly stamped, that was all the shafts I saw. The Propeller & Thrust shaft was inspected by the B Corporation Surveyor R. Steel. and away before I took over the job. I saw the test of these shaft being pulled in the presence of the B.C. Surveyor Mr. Steel that is the reason for them appearing on the report. The Crankshaft I never saw at any time.

I can only insist on the broken stamping the shafts I saw, and shall always insist on them doing it. Do you wish the Shipping report returned, I shall be glad to send it on.

I & Kincaid No 523. there are two Coupling nuts No Number on them, only LLOYDS sent on, this job being cancelled R.F. I think we ought to charge a fee for these.

With kind regards

Yours Sincerely Alexander Fletcher

W347-0055