


Babcock v Wilson. Borden No. 69/192.

Intended for Rotterdamse Droogdok Maatschappij
yard nos 503. & 505

Grimby 10833. - 4

It is concluded that the diameter of holes in the middle
circumferential seams are $31/32$ " diam that the pitch across
the wide water space is 13" and not $1\frac{3}{32}$ " & 16"
as stated on reports.

Await reply See reply
from Grimby before
forwarding reports.



HR

5. 4. 30

© 2020

Lloyd's Register
Foundation

W347-0133

Mr. Cooke



© 2020

Lloyd's Register
Foundation