

in, 10, 39.

to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME _____

"MOUNT MYRTO"

Report _____

Bal. _____

No. 7063

For the ~~CHIEF SHIP SURVEYOR~~ and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/02.*)

ature of Survey _____

DOCKING.

~~When due~~ _____

Noted.

Y Ruc

18.6.40

Subject to the dynamo governor being renewed.

1
lit 110234



© 2019

Lloyd's Register
Foundation