

2.11.20.

to Chief Surveyors _____

Received from Chief Surveyors _____

SEL'S NAME STTS "NAPIERSTAR" Report Snk No. 18668

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)


re of Survey 1st Entry When due _____ Revised Rules _____

✠ 100 A.1. (Steel) "With freeboard"

3 D^K (Stl), 4^K D^K (Stl) in No 1-2-3-5 & 6 holds

Cell D.B 404' 1419t, F.P.T 103t, A.P.T. 116t

F.K. ~~stuck~~ Keel forward of machinery space 140', 88.H, ft cm, Lloyd's A.C.P.
P 72', B 200', F 39'.



© 2019

Lloyd's Register
Foundation

W349-0232

183-27