

MARCH 6 1911

ed by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

EL'S NAME "ETHEL RADCLIFFE" Rpt. St.J No. 2896

e remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The class is subject to the sternframe solepiece E.W. 10.40 also rivets and plate edges under forefoot E.W. 10.40 being specially examined at the next dry docking and to stem and stem plating being dealt with at the Owners' convenience.

The ST. JOHN N.B. Surveyor reports the vessel afloat and on account of heavy weather damage repairs effected to a starboard bow shell plate.

It is submitted the vessel is worthy to remain as classed without record of survey, subject as above.

As Now, Subject, etc.



© 2020

Lloyd's Register Foundation

W35-0023

signed) a  
XXXXXX  
ther o  
repa  
r Y.M.  
te if on  
ed, Mon  
ards, &  
how as  
if we  
at letter  
No. of  
state if  
gth.....  
(on bu  
le lengt  
cker .....

Hawsers & Wa  
Standing and R