

S.S. "ESSO HOUSTON".

New York Report No.38176.


Emergency Trip Switches on Turbine Generators.  
-----

This matter has been discussed with  
Mr.J.S.Heck as suggested in the New York letter of the  
16th May.

Mr.Heck confirms that an error was made in  
stating that these switches were fitted on the sister ships  
"ESSO BAYONNE" and "ESSO BAYWAY".

He also states that the tests called for  
in a previous endorsement,dated the 27th April, have been  
satisfactorily carried out and that the generators have been,  
specially designed to run as motors with stable speed  
characteristics.

In these circumstances IT IS SUBMITTED no  
exception be taken to the omission of the switches required  
by Section 2, paragraph 11.

  
30th May, 1938.



© 2020

Lloyd's Register  
Foundation

W35-0164