

sent to Chief Surveyors 5-2-09

Received from Chief Surveyors

VESSEL'S NAME S.S. "Delfin"

Report Bel No. 645

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 21/5/92.)

Nature of Survey 6th P.S. etc

When due

In view of the information now received as to the position of the side lights in the vessel a freeboard of 3'-6" from statutory deck line 1" above wood main deck at side has been assigned in accordance with the Tables as a condition of classification on account of the vessel having been altered to the Aowing deck type

[Signature]
10/2/09



© 2021

Lloyd's Register Foundation

W353B/4 - 0008