

Reference H.

W. WEST.
SURVEYOR
ISAAC PERAL B.

LLOYD'S REGISTER,
LONDON.

REC'D FEB 1909
ANSR

Lloyd's Register of British and Foreign Shipping

Cádiz 30th Jan^y 1909

The Secretary London

Dear Sir

In answer to yours of the 24th ult in reference to the S.S. Delfin which vessel is now here in port, I beg to state that there has been no alterations in the sidelights since she came from England, she has sidelights all round the vessel just under what we may call the Spar or Promenade Deck, this has been the principal alteration that has been made to this vessel in Barcelona, which I have no doubt you are aware of; then there are six more sidelights on each side of vessel, in the centre, 8 inches in diameter, and 1 inch from centre to the water, at the draft the vessel is now, being 8 feet 6 inches forward, and 14 feet aft, there being no other openings in vessel's sides, her usual sailing draft being 11 feet forward and 16 feet aft. The Cargo doors this vessel formerly had in her sides, have been gone away with, I may state that these vessels get very little cargo, rarely they get 100 tons, they are Mail boats,

Sir I remain
Your Obedt Servt
William West



© 2021

Lloyd's Register
Foundation

W353814-0009

Referred to the Chief Ship Surveyor.

al
FEB -5 1909

Also for Mr. S. A. Hill to note.



© 2021

Lloyd's Register
Foundation