

1.

Sent to Chief Surveyors

27. 1 04

Received from Chief Surveyors

VESSEL'S NAME

bh Currydce

Report

Bas No. 864

For the CHIEF SHIP SURVEYOR ~~ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/32.)

Nature of Survey

S S No. 1

When due

6 02

It is submitted the owner of this vessel should be informed it appears from a letter received from the Society's Surveyors that the oxidation at the back of the frames in the "Currydce" is such as to unduly distress the riveting through frames and shell. and it is considered the Surveyors' recommendations in regard to the removal of this oxidation and re-riveting of frames and shell should be complied with in order that the vessel may be eligible to retain the Society's classification. The other recommendations made by the Surveyors are also approved.

The owner should be requested to state definitely whether it is intention to proceed further with the Special Survey in order to retain the vessel's class.

B 27/1/04

J M



© 2021

Lloyd's Register
Foundation

W35434-0021