

Chief Surveyor 11-2-99

Received from Chief Surveyor

2

VESSEL'S NAME *San Agnes Oswald* Report *Cal* No. *1352*

The remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

S. S. No. *2*

The S.S. No. *2* has now been held, and the following repairs done (due to wear & tear):— *Shee fitted to stem, one bow plate and rudder plating repaired, fore-castle deck renewed, pumps repaired, and minor repairs.*

*The poop deck has been temporarily repaired by sheathing, and it is proposed to postpone the permanent repairs until the vessel's arrival at a home port. The Surveyor considers the deck as repaired for another twelve months.*

It is submitted the vessel is worthy to remain classed *100A1*

with record of Survey *1-99* and notation of S.S. *Cal*

*Nº 2-99*

~~as recommended.~~ *when the poop deck has been permanently repaired or renewed.*

*100A1  
1-99 Cal  
S.S. Cal Nº 2-99* } *when etc*



© 2021

*John N*  
Lloyd's Register  
Foundation  
*14/1/99*