

Sent to Chief Surveyor 8/9/92.

Received from Chief Surveyor

VESSEL'S NAME *Waverley*Report *Cal* No. *788*

The remarks of the Chief Surveyor are desired on this Case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

*Damage*

The accompanying press copy of damage survey report is a statement of the repairs which have been effected and are given on the Calcutta report No 788 which received the consideration of the Committee on the 19<sup>th</sup> ult.

To complete the S.S. No. the tank top under the Boiler has to be made tight, please see endorsement 19892 & 31892.

It appears from the Owners letter the work in connection with the tank top was not quite completed on the 13<sup>th</sup> August and is to be finished on the vessels return to Calcutta from Bombay.

The Calcutta Surveyor was written to on the subject on the 31<sup>st</sup> ult and action shown he deferred till his reply is received.

For Mr Hill Sonose.

*HM 8/9/92*

© 2021

Lloyd's Register  
Foundation