

S.S. "Waverley" 2022 Tons.

This vessel arrived here for effecting repairs, she having grounded in Madras Harbour, and in accordance with our instructions, she was at once placed in Merewether Dry Dock, where I jointly with Mr. Jas Moir surveyed her & found the bottom seriously damaged on the Starboard side.

As no Docks are available here for the length of time required for repairing the vessel - she had been temporarily repaired here in order to proceed to Calcutta in ballast for permanent repairs - I beg to enclose copies of our reports given to the Captain of the said vessel. Mr. Jas Moir has surveyed the Machinery of this vessel for Lloyds S.S. N^o 1. following N^o 3 - whose report I beg to enclose herein - I wrote to Mr. McKellar the Society's Surveyor at Calcutta - copy of which I enclose herein.

I remain
Sir

Your most obedient servant.

A. S. Clark



Lloyd's Register
Foundation

W35785-0019

M32582-0014

and Chief Engineer Surveyor
of the City Surveyor

[Signature]

1/2/92

Wm for
Indest

[Faint handwritten text, possibly a signature or address]

[Faint handwritten text, likely bleed-through from the reverse side of the page]

LD'S REGISTER,
LONDON.
RECEIVED 1 FEB. 92
ANSR

Ram. 16.1

Mr. J. Laake

Enc rpts to re
S.S. Akbar

"D. Embriage" Arthur
Head "Niagara"
H. W. Overley



© 2021

Lloyd's Register
Foundation