

S.S. "SHIRLEY"

---

Submitted the Calcutta Surveyor be informed with reference to his letter of the 12th November that if the condition of the decks and bulkheads was such that in his opinion the repairs to these parts should not have been delayed beyond the end of November, he should have made a definite statement to this effect on Report No. 3068 instead of suggesting that these parts be dealt with when the furnaces were under repair, and also have furnished full particulars of the deterioration which had taken place in these parts.

*C. B. E.*

6.12.12.

*Copy of Lr. 74/9/12 to the Master  
shd have been sent with his  
Report*



© 2021

Lloyd's Register  
Foundation

W35386-0062

W25456-0041

5E00-98655M

W100-98155M