


Bk. "ELFLEDA".

It is submitted the Surveyors be informed that in this case, having regard to the size and position of the auxiliary motors placed in the sailing vessel, it is not considered necessary that a bulkhead or recess should be fitted in the position stated in their letter. It may be noted that the bulkhead at the forward end of the machinery space has been efficiently constructed and stiffened as a watertight bulkhead.

Lr. 21.6.15

C.T.

  
21.6.15

I.M.



© 2021

Lloyd's Register  
Foundation