

Urgent

Chief Surveyors 29 9 11

Received from Chief Surveyors

EL'S NAME SSS Ciudad de Pinar Report Rur No. 60771

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey

Recluse

When due

Case for Authorization

It is submitted the Danzig Surveyor be informed that in order to entitle this vessel to be recommended to the Committee to have her class reinstated in the Register Book it will be necessary for all the requirements of the 2nd Vellor to be complied with ~~immediately~~, and for the repairs recommended in Barcelona reports No 768 & 814 & Newcastle report No 60771 to be carried out. Copies of these reports should be sent to the Danzig Surveyor for his information.

It is further submitted that the Danzig Surveyor might be authorized to hold the Survey, but that in the circumstances Mr. Dykes should join in the Survey and both the Danzig and Hamburg Surveyors should be so informed.

H.R.H.

M. R.B.H.

E. L. L.

M. J. H.

29/9/11

Lloyd's Register Foundation

W362B15-0010