

Damages No 56.

And W^t Latona of 286 tons.

The vessel left Timaru (New Zealand) loaded with a full cargo of wheat for Australia, and ~~afterwards~~ subsequently put into Port Chalmers, Leaky. She was surveyed in dry dock by Mr Russell, the Society's Surveyor at that port from the 29th May to July 3rd (25 visits) During this time it would appear that all the recommendations made by Mr Russell were carried out, and no objection appears to have been taken by the Owner's Agent to these recommendations. The vessel was retreenailed from bilge to planks below (2300 treenails) in addition to being recaulked all over, and other repairs. On being undocked it was found that ^{when loaded} she made much water for a few hours - which is not uncommon with a newly treenailed vessel - and this amount was subsequently diminished to $\frac{3}{8}$ of an inch per hour. A certificate is made to read that though a survey was held on the vessel by several Surveyors, who pronounced the vessel seaworthy and capable of proceeding on her voyage, Mr Russell deferred sending in his report ^{the date of} from his last visit say July 3rd till July 15th - for the purpose of ^{alleged of} "overriding" the reports made by others. Mr Russell in his report



to the Committee sets forth the repairs, which were done, as before stated, but in his general observations states that "In consequence of the rotten condition of the timbers remaining in hull &c." he is of opinion that the vessel is not entitled to retain her character A1 on the Register book.

It is submitted that after a careful perusal of the reports and correspondence bearing on this case, as appended, it is impossible without further communication with Mr Russell to express any opinion on the merits of the case for the guidance of the Committee.

Wm

24/11/84

Wm

S.H.C



© 2021

Lloyd's Register
Foundation