

Method of reversing Engines... Are the cylinders fitted with safety valves... YES Are the exhaust pipes...  
FORCED Thickness of cylinder liners... 43MM

Foylebank.

Bel 10509

It is submitted that, before this report receives consideration the Bel Surveyors be requested to send the approved plans of the boiler to this office.



© 2019

LL's Register  
Foundation

28/11/30

W37-0081

What pipes pass through the deep tanks... the machinery and all boiler mountings accessible at all times.