

1E

Chief Engineer Surveyor _____

Received from Chief Engineer Surveyor _____

NAME T.S.M.V. "CONCH"

Rpt. gls

No. 51965.

ks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Engine Oil Engines 4 S.C.S.A.

RETAIN

If Boilers fitted with forced draught ✓

Tail Shaft. If fitted with a continuous liner

yes

If fitted with an outside gland of

approved type

no


This vessel's machinery appears to have been built in accordance

the Rules and the approved plans, and it is submitted she is

able to be classed

+ LMC 12-31

2 DB. 150 LBS/sq IN.


 3-12-31



© 2019

Lloyd's Register
Foundation

W372-0099