

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

14th March, 1932.

Dear Sir,

M.

With reference to your letters of the 29th ultimo and 3rd instant regarding the failure of links of the chain cable of the Twin Screw Motor Vessel "CONCH", I am directed to inform you that the matter has been very carefully looked into, and that, after consideration of the information and remarks forwarded, the explanation arrived at, namely that the original link fractured through jamming in the mouth of the chain pipe, is concurred in.

At the same time the Superintendent of the Glasgow Proving House is being advised that in view of the enquiries made it is considered that his action in removing the four additional defective links from the chain cable was in order.

I am, Dear Sir,

Yours faithfully,

Secretary.

H. Green, Esq.,
Superintendent,
Lloyd's Proving House,
NETHERTON,
Dudley.



© 2019

Lloyd's Register
Foundation

W372-0126