

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

14th March, 1932.

Dear Sir,

M.

Reverting to your letter of the 5th January regarding defective links found in the chain cables of the new Twin Screw Motor Vessel "CONCH" (see Glasgow Report No. 52041), and to subsequent correspondence, I am directed to inform you that the matter has been very fully investigated.

In view of the remarks and opinions expressed by the Proving House Superintendents and by the Surveyor, the explanation arrived at, namely that the original link fractured through jamming in the mouth of the chain pipe, is concurred in. Further, the Superintendent of the Glasgow Proving House is being advised that, in view of the results of the enquiries made, it is considered that his action in removing the four additional defective links from the chain cable was in order.

I am, Dear Sir,

Yours faithfully,

The Secretary,  
GLASGOW.



Secretary.

© 2019

Lloyd's Register  
Foundation

W372-0127